TORONTO WORK REPORT as of October 6, 2025

ONGOING

Location	Contractor	Job Type	Manpower	Duration
PetroCan Clarkson	CAM	Boiler outage / Maint	. 23 BM	2-3 weeks
Atlantic Pkg	TIW	New Tank	4 BM	5 months
Pierson Airport	Horton CBI	Floating roof	4 BM	wrapping up
PetroCan Clarkson	Platecon	Tank repairs	5 BM	5 weeks
Kinetics Etobicoke	BWXT	Hot Cell Fab.	8 BM	8 weeks
PetroCan Clarkson	B&W	Boiler repairs	4 BM	2-3 weeks
UPCOMING				
PetroCan Clarkson	CommonWeal	th Stack repairs	5 BM	5 weeks
Goreway Power	Barclay Const	. Maint. Outage	3 BM	10 days
Atlantic Packaging	TIW	Tank	TBD	Long Term
PetroCan Clarkson	CAM	Spring outage	100+/-	3-4 weeks
Hanover	LandMark	Water tower	TBD	LT
Teeswater	LandMark	Water Tower	TBD	LT

