

ENERGY SECTOR (EPSCA) WORK REPORT

April 9, 2025

ONGOING WORK

APPENDIX 'A'	BRUCE POWER	OUTAGE WORK	42 BM
E.S. FOX	BRUCE POWER	BALANCE OF PLANT	14 BM
E.S. FOX	BRUCE POWER	U4 SPRING CANS	9 BM
E.S. FOX	BRUCE POWER	U4 BULKHEAD INSTALL	77 BM
BRUCE POWER	BRUCE POWER	RPC – GREENMAN	19 BM
AECON / SHORELINE	BRUCE POWER	U3 MCR/SGRT - REFURBISHMENT	475 BM
AECON/SHORELINE	BRUCE POWER	U5 SFCR	12 BM
EMC	BRUCE POWER	HEAT EXCHANGER INSPECTION	2 BM
E.S. FOX	DARLINGTON	BALANCE OF PLANT, COBALT 60	12 BM
BWXT	DARLINGTON	PMSR – PRIMARY MOISTURE SEPARATOR REPLACEMENT	30 BM
BWXT	DARLINGTON	PRIMARY SIDE CLEAN BOILER OPEN/CLOSE	24 BM
OPG	DARLINGTON	RPC - GREENMAN	17 BM
AECON / CANATOM	DARLINGTON	U4 - REFURBISHMENT	400 BM
BLACK & MCDONALD	DARLINGTON	ON-SITE WORK TASKS – TRF OUTAGE	14 BM
BLACK & MCDONALD	PICKERING	ON-SITE WORK TASKS	8 BM
OPG	PICKERING	RPC – GREENMAN	2 BM

UPCOMING WORK

BWXT	BRUCE POWER	U3 STEAM DRUM SEPARATOR REPAIR – MAY 20th	60 BM
AECON/SHORELINE	BRUCE POWER	U4 FEEDER CUT OUT – JUNE / JULY	140 BM
AECON/SHORELINE	BRUCE POWER	U3 LOWER FEEDER INSTALL – JULY / AUG	90 BM
AECON/SHORELINE	BRUCE POWER	U4 FUEL CHANNEL REMOVAL – SEPT / OCT	40 BM
APPENDIX 'A'	BRUCE POWER	U2 OUTAGE – AUG / SEP	86 BM
BLACK & MCDONALD	DARLINGTON	U3 OUTAGE – DEC / JAN	80 BM